



Ø .250 THRU -173
MATCH DRILL WITH HOLE
PATTERN OF -75
MS27039-1-10 SCREW
NAS1149F0316P WASHER
2 PLACES

MATCH DRILL COVER TO HOLES IN
ANGLE BRACKETS. ATTACH USING
MS27039-1-10 SCREW
NAS1149F0316P WASHER
6 PL (3 PL OPP)




MS27039-1-10 SCREW
NAS1149F0316P WASHER
2 PLACES





CUTOUT ENSOLITE FOR INTERFACING WITH -11 & -13 ASSEMBLIES

② -21 UPPER BLADE SUPPORT AND COVER ASSEMBLY

SCALE 0.500



Ø .250 THRU -181
MATCH DRILL -181 WITH
EXISTING HOLE PATTERN
OF -79
MS27039-1-10 SCREW
NAS1149F0316P WASHER
2 PLACES



② -23 LOWER BLADE SUPPORT AND COVER ASSEMBLY


SCALE 0.500

PREMIER AVIATION, INC.			
2000 Aviation Parkway, Grand Prairie, Texas 75050			
SIZE	CODE	REV	DATE
D	OSUV8	B67-43001	81
SCALE:	1"	10"	45

ORIGINAL

RELEASED

el6et



PREMIER AVIATION, INC.
 2001 Aviation Parkway, Grand Prairie, Texas 75050

DATE	REV	BY	CHK
D	OSUV8	B67-43001	RL

ORIGINAL

Date: Monday, 27/10/2008 1:03:56 PM
User: Melanie Fauteux

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: REWORK PB674300179

Job Number: 42972

Part Number: PB674300179

Job Number:



Seq. #:

Machine Or Operation:

Description :

5.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

08/10/28 @

6.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

08/10/28 @

7.0

POWDER COATING

POWDER COATING



Comment: POWDER COATING

m/B2316

POWDER COAT GREEN SANDTEX
PER QSI 005
INSTALL BOLTS AND NUT PLATES

start: 1:30
Temp: 320°
Finish: 2:00

FL 08/10/28

8.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

08/10/28 (12)

9.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

REINSTALL ORIGINAL PARTS

SAD 08/10/28 (14)

10.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

08/10/29 @

11.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Location can

RETURN TO STOCK UNDER ORIGINAL BATCH NUMBER

08/10/29 @

12.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

08/10/30

Job Completion



MF 08-10-29

Date: Monday, 27/10/2008 1:03:56 PM
 User: Melanie Fauteux

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: REWORK PB674300179
Job Number	: 42972		
Estimate Number	: 10804		
P.O. Number	:	Part Number	: PB674300179
This Issue	: 27/10/2008 S.O. No. :	Drawing Number	: REWORK PB674300179
Prsht Rev.	: NC	Project Number	:
First Issue	: 27/10/2008 Type : LARGE FAB ASSY	Drawing Revision	:
Previous Run	: 00015	Material	:
Written By	:	Due Date	: 27/10/2008 Qty: 1 Um: Each
Checked & Approved By	: <u>MF 08-10-27</u>		
Comment	:		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

PULL FROM STOCK PB674300123 B 4137 QTY X 1
 PER NCR 08-104
 REMOVE ALL PARTS
 IDENTIFY AND STOCK

* SAD 08/10/27 @

2.0	LARGE FAB 1	LARGE FABRICATION RESOURCE 1
-----	-------------	------------------------------



Comment: LARGE FABRICATION RESOURCE 1

1. CUT OFF WRONG PB6743001179
 2. GRIND WELD FLUSH AND/OR REMOVE POWDER COAT

SAD 08/10/27 @

3.0	QC5	INSPECT WORK TO CURRENT STEP
-----	-----	------------------------------



Comment: INSPECT WORK TO CURRENT STEP

SAD 08/10/27 @

4.0	LARGE FAB 1	LARGE FABRICATION RESOURCE 1
-----	-------------	------------------------------



Comment: LARGE FABRICATION RESOURCE 1

WELD PB6743001179 B 41565 TO CORRECT PART

Per Q57004

PL 08-10-27 (X1)